

Dane aktualne na dzień: 02-10-2026 02:33

Link do produktu: <https://www.mototraktor.pl/lozysko-case-ford-massey-ferguson-893373m91-84356153-84128120-p-11465.html>



ŁOŻYSKO CASE FORD MASSEY FERGUSON 893373M91 84356153 84128120

Cena	49,00 zł
Dostępność	Dostępny
Numer katalogowy	893373M91
Kod producenta	ŁŻ15
Producent	TIMKEN

Opis produktu

ZASTOSOWANIE:

CASE:

433, 523, 533, 624, 633, 644, 724, 733, 743, 743XL, 744, 745, 745S, 745XL, 844, 844S, 844XL, 845, 845XL, 1046, 1246, 946, 1055, 1055XL, 955, 955XL, 1056, 1056XL, 856, 856XL, 956, 956XL, 5120, 5130, 5140, 5150, 5220, 5230, 5240, 5250, MX100, MX100C, MX110, MX120, MX135, MX80C, MX90C

FENDT:

Farmer 102, 102LS, 102LSA, 102S, 102SA, 103, 103LS, 103LSA, 103S, 103SA, 104LS, 104LSA, 104S, 104SA, 105, 105LS, 105LSA, 105S, 105SA, 106LS, 106LSA, 106S, 106SA, 108LS, 108LSA, 108S, 108SA

Farmer 200S, 200SA, 200V, 200VA, 201S, 201SA, 203V, 203V/II, 203VA, 203VA/II, 204V, 204VA

FORD:

2000, 2000 US Built, 2100, 2110, 2120, 2150, 2300, 231, 231 US Built, 2310, 233, 2600, 2600 US Built, 2600N, 2600V, 2610, 2910, 3000, 3000 US Built, 3055, 3100, 3120, 3150, 3190, 3300, 3310, 333, 3330, 3550, 3600, 3600 US Built, 3600N, 3600V, 3610, 3900, 3910, 3910N, 4000, 4000 US Built, 4000SU, 4100, 4110, 4110N, 4140, 4600, 4600SU, 4610, 531, 531 US Built, 600, 601, 700, 701, 800, 801, 900, 901, Dexta, Jubilee, NAA, Super Dexta

LANDINI:

7830, 7860, 8860, 9500, Large 9550

MASSEY FERGUSON:

1080, 1085, 130, 135, 135 US Built, 140, 158, 165, 168, 175, 178, 185, 188, 20D, 2200, 235, 245, 250, 255, 265, 270, 275, 282, 283, 285 (FR), 285 US Built, 290, 290 US Built, 298, 30, 3050, 3060, 3065, 30D, 30E, 31, 3165, 352, 355, 360, 362, 375, 375E Brazilian, 383, 390, 390E Brazilian, 393, 396, 398, 399, 40, 565, 575, 590, 595, 65, 65 US Built, 670, 675, 690, 698, 698T, 699, 765

WYMIARY: 31,7 x 59,1 X 16,7 mm

NR KATALOGOWY: 202518C91, 202514C91, K620076, 80036726, K962984, K24659, D5NN1201A, D5NN1202A, 1597, 3142103R91, 179080, 47923369, 36723, 651815R91, 651814R1, 651817R1, 84356153, 7900, 80036723, 651818R91, 36725, 36726, 84128120, 198056, 36726, 36978, 279900, 36723, V1972, LDC1076010010, H602957R91, PECP1446, MC01010008, H651817R1, GB4299, C5NN1201A, C5NN1202A, 8A1201C, 84356153, BU146197, BMBLM67010, 83910702, CBPN1200F, D5NN1202B, D5NN1202A, 860468, 860532, D5NN1201A, 860270, 80036723, 80036726, 80786041, 83910703, AE42998, RLT010, 651817R1, 651818R91, 354361X1, 354370X1, 893373M91, 354369X1, X623168230000, 1871250, 21882330, 893373M91, 893373M92, 893373V91, 9227510018, 923458049, 9234580490