

Link do produktu: <https://www.mototraktor.pl/sprezyna-zaworu-massey-ferguson-landini-ford-new-holland-p-13934.html>



SPRĘŻYNA ZAWORU MASSEY FERGUSON LANDINI FORD NEW HOLLAND

Cena	9,00 zł
Dostępność	Dostępny
Numer katalogowy	731154M1
Kod producenta	MF1083

Opis produktu

Zastosowanie

Ford / New Holland

DEXTA, SUPER DEXTA

Landini

4000, 4500, 4530, 5000, 5500, 5530, 5830, 5840, 5860, 5870, 6000, 6030, 6040, 6060, 6070, 7000, ADVANTAGE 55, ADVANTAGE 60, BLIZZARD 50, BLIZZARD 60, C4500, C4830, C5000, C5500, C5830, C6000, CF4830, CF5030, CF5830, CF6030, CF6060, GLOBUS 50, REX 55, REX 60, TREKKER 55, TREKKER 60

Leyland

245, 253, 502

Massey Ferguson

133, 135, 135 US BUILT, 148, 150, 152, 154, 155, 158, 165, 165 US BUILT, 203, 205, 20B, 20D, 20E, 20F, 2135, 2200, 230, 230 US BUILT, 233, 234, 235, 240, 245, 250, 2500, 253, 254, 255, 260, 30, 302, 304, 30E, 3165, 340, 342, 35, 35 US BUILT, 350, 353, 354, 355, 35X, 360, 363, 40, 40B, 40E, 50, 550, 560, 65, 65 US BUILT, 765

Perkins

A3.144 (CB), A3.152 (CD), A4.192 (JB), A4.203 (JD), AD3.152 (CE), AD4.203 (JE)

Nr katalogowy

731154M1