

Link do produktu: <https://www.mototraktor.pl/czujnik-cisnienia-oleju-new-holland-ford-504084983-p-9311.html>



CZUJNIK CIŚNIENIA OLEJU NEW HOLLAND FORD 504084983

Cena	79,00 zł
Dostępność	Dostępny
Numer katalogowy	504084983

Opis produktu

ZASTOSOWANIE:

FORD:

5610S, 6610S, 7610S

NEW HOLLAND:

LB115B, LB110B, LB90B, LB95B
5610S (Mexico), 6610S (Mexico), 7610S (Mexico), T4.65 V, T4.75 V/N/F, T4.85 V/N/F, T4.95 V/N/F, T4.105 V/N/F, T4.115, T4.55 PowerStar (Tier 4A / Tier 3), T4.65 PowerStar (Tier 4A / Tier 3) , T4.75 PowerStar (Tier 4A / Tier 3) , T4.75 , T4.85 , T4.95 , T4.105, T4020, T4030, T4040, T4050, T4020 Deluxe, T4030 Deluxe, T4030 Deluxe (Japan), T4040 Deluxe, T4050 Deluxe, T4030F, T4040F , T4050F, T4060F, T4030N, T4040N, T4050N, T4060N, T4020V, T4030V, T4040V, T4050V, T4060V, T5.95, T5.105, T5.115, T5.95 Electro Command, T5.105 Electro Command, T5.115 Electro Command, T5030, T5040, T5050, T5060, T5070, T6010 Delta, T6010 Plus, T6020 Delta, T6020 Elite, T6020 Plus, T6030 Delta, T6030 Elite, T6030 Plus, T6050 Delta, T6050 Elite, T6050 Plus , T6070 Elite , T6070 Plus, TD5010, TD5020, TD5030, TD5040, TD5050, TD5030 (Japan), TD5040 (Japan), TD4020F, TD4030F, TD4040F, TK4040M, TK4050, TK4050M, TK4060, TK4020F, TK4020V, TK4030, TK4030V, TK4030F, TK4040, TL100A, TL70A, TL80A, TL90A, TM7010 (Brasil), TM7020 (Brasil), TM7030 (Brasil), TM7040 (Brasil), TN85A, TN95A, TN85DA, TN95DA, TS6, TS6.110 (Mexico), TS6.120 (Mexico), TS6.125 (Mexico), TS6.140 (Mexico), TS6000, TS6020, TS6040, TS6030, TS6000 (Inter. incl. Mexico), TS6020 (Inter. Incl. Mexico), TS6030 (Inter. Incl. Mexico), TS100A Delta, TS110A Delta, TS115A Delta, TS130A Delta
LM5060 PowerShift, LM5040 PowerShift, LM5080 PowerShift

NR KATALOGOWY: 2852889, 504084983