

Link do produktu: <https://www.mototraktor.pl/zestaw-naprawczy-pompy-wody-massey-ferguson-landini-3637615m91-p-5716.html>



ZESTAW NAPRAWCZY POMPY WODY MASSEY FERGUSON LANDINI 3637615M91

Cena	149,00 zł
Dostępność	Na zamówienie
Numer katalogowy	3637615M91

Opis produktu

ZASTOSOWANIE:
MASSEY FERGUSON:
155, 158, 158F, 158S, 158V, 165, 260, 65, 560, 765, 865, 30, 302, 304, 3165, 3303, 3305, 356, 40B, 50

LANDINI:
6500, 6505, C6000, 6000, 6000Special, 7000Special

TYP SILNIKA:
A4.236 - Perkins
AD4.203 - Perkins
A4.192 - Perkins
A4.203 - Perkins
AD4.203 - Perkins

NR KATALOGOWY: 3637615M91, 3639521M1, 3640324M91, 3641351M91, 3641393M91, 59140, 59652, 732591M91, 741657M91, 89024, U7LW0027, U7LW0045, U7LW0076, U7LW0092, U7LW0101

A	B	C	D	E	F	F2	G	H	I	Turbi ne th ickne ss	J	K	Seal thick ness
130,00	45,00	8,00	77,00	16	19	15	15,00	80,00	15,90	20,50	37,00	16,00	22,60