

Link do produktu: <https://www.mototraktor.pl/zestaw-uszczelek-silnika-dol-massey-ferguson-claas-landini-4224292m91-p-6262.html>



ZESTAW USZCZELEK SILNIKA DÓŁ MASSEY FERGUSON CLAAS LANDINI 4224292M91

Cena	120,00 zł
Dostępność	Dostępny
Numer katalogowy	4224292M91

Opis produktu

ZASTOSOWANIE:

MASSEY FERGUSON:

1004T, 1007, 362, 365, 367, 373, 374, 375, 376C, 377, 382N, 383, 384AP, 387, 390, 390T, 393, 394, 396, 397, 397T, 398, 3050, 3055, 3060, 3065, 3065S, 3070, 4225, 4240, 565, 575, 590, 675, 690 , 698T

LANDINI:

6550, 7550, 8550, 6500, 7500, 8500, 6880, 6880VM, 7880, 7880VM, 8880, 8880HC, 8880VM, 9080, 9080HC, 9880, 9880HC

CLAAS:

COSMOS, CORSAR, COMPACT, COMPACT 30, MERCUR, MATADOR, MATADORSTANDARD, CONSUL, PROTECTOR, MERCATOR, MERCATOR 50, DOMINATOR, DOMINATOR 56, DOMINATOR 86, DOMINATOR 38, DOMINATOR 48, DOMINATOR 68

TYP SILNIKA:

- A4.236 - Perkins
- A4.212 - Perkins
- A4.236 - Perkins
- A4.248 - Perkins
- A4.318 - Perkins
- A4.41 - Perkins
- AT4.236 - Perkins

NR KATALOGOWY: 3637600M91, 3637753M91, 3638515M91, 3640719M91, 4224292M91, 4224292Z91, 68006, 68009, 68011, 68013, 68032, 747191M91, 82885, 85007, 85781, 85795, 86979, 92432, 92440, 94475, U5LB0003, U5LB0004, U5LB0005, U5LB0016, U5LB0035, U5LB0037, U5LB0045, U5LB006, 3637600M91, 3637753M91, 3638515M91, 3640719M91, 4224292M91, 4224292Z91, 4224369M1, 4224369Z91, 68006, 68009, 68011, 68013, 68032, 747191M91, 82885, 85007, 85781, 85795, 86979, 92430, 92432, 92440, 94475, U5LB0003, U5LB0004, U5LB0005, U5LB0016, U5LB0035, U5LB0037, U5LB0045, U5LB006, U5LB0145